

No. 238

Survey made for Joseph Horner of the S.E. 1/4 of the S.W. 1/4, and the S.W. 1/4 of S.E. 1/4, of Section 34, of Town 4 N. of Range 4 West of 4th. Principal Meridian N. 3/4

Commencing at 1/4 Post, between Sec. 34 & 35. Thence West 79.96/100 chs. to 1/4 Post between Sec. 33 & 34. Corrected back

From 1/4 Post between Sec. 27 and 34, South 80.1/100 chs. to 1/4 Post on South line of said Sec. 34.

Original { N. 0. 20 N. 26 E. 215 }  
{ No 10 N. 73 W. 345 } Bearings

Corrected back to 1/8th. Sec Post - at N.E. cor. of said S.E. 1/4 of S.W. 1/4

{ Br. 0. 12 S. 78 W. 110 }  
{ Elm 16 N. 27 1/2 E 19 }

From 1/4 Post on South line of said Section 34, East 39.9/100 chs. to corner of Sections 34 & 35 - Corrected to 1/8th Sec Post

{ N. 0. 15 S. 15 1/2 W. 28 }  
{ do 12 N. 10 E. 73 }

Thence North 40.16/100 chs. to 1/8 Sec. Post - Corrected back to 1/16th. Sec. Post - at N.E. corner of said S.W. 1/4 of S.E. 1/4

{ Elm 14 N. 3 1/4 W. 45 }

From 1/4 Post on South line of said Sec. 34, West, 40.9/100 chs. to corner of Sec. 33 and 34 - Corrected back to 1/8 Sec Post

{ N. 0. 18 N. 4 1/2 E 41 }  
{ do 12 N. 7 1/4 E 78 }

Thence North, 40.9/100 chs. to 1/8th. Sec Post - Corrected back to 1/16th Sec Post at N.W. corner of said S.E. 1/4 of S.W. 1/4

{ Br. 0. 12 S. 44 1/2 E. 25 }  
{ do. 14 N. 39 1/2 E 28 }

Thence Bleya - East to 1/16th Sec. Post  
Dec. 7th. 1840.

Gas. E. Freeman

Dist. Suror.

Survey of the East No 23, of

Commencing North 80.1/100

Original Thence Corner From

to 1/4 Post between Post - at

Thence

Thence

From 1/4 Post Thence, Corrected

From 1/4 Post between Thence Corrected

to 1/8th. Sec. Dec. 8th 1840

{ East and West van 8.23' E }  
{ North and South do 11.70' E }

{ East and West van 11.0' E }  
{ North and South do 8.45' E }