

NO. 19
Field notes of Survey of E. 1/2 of S. W. 1/4 of Section
16 Township 5 North Range 5 West, Made for
Samuel Parker, June 28th 1853.

Beginning at corner of Sections 16, 17, 20 & 21
random East var. $8^{\circ}12' E$, at 40.07 1/2 chains intersect
7 links north of 1/4 Section post. Thence correct
West 20.03 3/4 chains & set post for 1/8 Section corner,

Then from 1/4 Section post on line between
Sections 16 & 21, random North var. $8^{\circ}45' E$ East
and intersect 10 links East of 1/4 Section post
on line between Sections 9 & 16. Then from 1/4 Section post on
line between sections 15 & 16, random thence West
var. $8^{\circ}12' E$, and from intersection of true North
and South line through center of Section,
Measure thence West & 40.08 chains intersect
section line 65 links South of 1/4 Section post
Corrected thence East 20.04 chains & set post
for 1/8 Section corner, and at 40.08 chains corrected
and set post for 1/4 Section corner

A true record of notes of said Survey

John G. Clark

Deputy County Surveyor

N^o 20
Notes of Survey made for Waldo Brown of
the S. W. 1/4 of the N. E. 1/4 of Sec 16, Township 5 North
Range 5 West, June 28th 1853 Frederick N. Gardick
& William Young Chairmen having first been
duly sworn.

Beginning at 1/4 Section post on line between
Sections 15 & 16, random thence West var $8^{\circ}12' E$ East
at 40. chains set temporary center post, at
about 80. chains intersect Section line 65 links
South of 1/4 post on line between Sections 16 & 17,

Then from 1/4 Section post on line between Sections
16 & 21 run a random line North, intersect corrected
East & West line through center of Section, 26 links
West of temporary center post. Thence from point
of intersection continued line North at same
variation, at 40.26 chains intersect Section line
10 links East of 1/4 Section post on line between
Sections 9 & 16. Corrected thence South 20.13 chains
& set post 1/8 Section corner, Then correct & set
post for 1/4 Section corner in center of Section,
Thence correct East 20.15 1/2 chains & set post
for 1/8 Section corner & took bearing B. Oak $82^{\circ} E 132$
links.

Then from 1/4 Section post on line between
Sections 9 & 16, ran East on a random line at a
variation of $7^{\circ}25' E$, at 40.31 intersect at corner of
Sections 9, 10, 15 & 16, Thence random South $9^{\circ} E$, at
40.21 chains intersect 17 links East of 1/4 Section
post. Thence corrected North 20.10 1/2 chains & run
random West var $7^{\circ}30' E$ & intersect 3 links South
of 1/8 Section post on West side of the N. E. 1/4
of Section 16, Then from 1/8 Section post on South
side of N. E. 1/4 of Section 16 random North var $8^{\circ}45' E$,
& intersect at 1/8 Section post on North side of
said N. E. 1/4 of Section 16. Thence corrected South
and set post for corner to 1/16 Sections in center
of said N. E. 1/4 of Section 16.

A true copy of notes of said Survey.

John G. Clark

Deputy County Surveyor