

27

Notes of Survey made in Section 1 Township 4 North Range 6 West April 12<sup>th</sup> 1854 by Solomon Goodrich Deputy County Surveyor of the S.E. 1/4 of the N.W. 1/4 and the N.E. 1/4 of the S.W. 1/4 for Henry Guelich, of the N. 1/2 of the N.W. 1/4 of S for William Howard, and of the W. 1/2 of the S.W. 1/4 for M. Scott. Anson H. Thomas and Joseph Wang chainmen first duly sworn.

Commenced at 1/4 Post on North side of said Section 1 Variation 9° 30' East run South at 77.50 intersect Section 16 1/2 links East of 1/4 Section corner where bears White oak 22 S 87 3/4 W 155 links (new bearing the old one being destroyed)

Thence corrected North Par 5° 57' East at 20.00 chains set temporary 1/6 Section corner at 11. chains set temporary 1/4 Section corner. Then from quarter Section corner between Sections 1 and 2 ran East Variation 10° East at 39.32 chains intersect 7 links North of temporary Section corner at 79.17 chains intersect range line 12 links South of quarter Section corner. Thence corrected West Variation 10° 15' East at 39.73 1/2 chains set post for quarter Section corner in mound. Thence corrected West Par 9° 54' East at 59.60 1/4 chains set post for 1/4 Section corner. It took 18 S 72 3/4 W 192 links. It took 18 N 81 1/4 W 222 links. Then from center post corrected South Variation 8° 39' East at 20.00 chains established 1/6 Section corner in mound. Then from center post corrected North Par 9° 15' East at 20.00 chains set post for 1/6 Section corner in mound.

Then from 1/4 Section corner between Sections 1 & 12 ran West Variation 10° East at 40.00 chains fell 30 links West of corner of Sections 1, 2, 11 & 12. Thence corrected East Variation 9° 36' East at 20.00 chains set post for 1/4 Section corner. It took 18 N 79 1/4 W 236 links. Oak oak 8 N 41 1/2 W 44 links.

Then from corner of Sections 1, 2, 11 & 12 hence bears White oak 12 N 78 1/2 W 45 links (new bearing)

North Variation 10° East at 39.75 chains fell 16 links to the East of 1/4 Section corner. Thence corrected South Variation 10° 14' East at 19.87 1/2 chains set post for 1/6 Section corner. Sugar 10 S 87 1/2 W

28

19 links N 87 1/2 W 20 N 56 1/4 W 35 links. Thence East Variation 10° East at 20.00 chains set temporary 1/6 Section corner. at 40.12 chains fell 22 links North of 1/6 Section corner. West corrected Variation 9° 41' East at 20.06 set temporary 1/6 Section corner. Then North from 1/4 corner West of 1/4 Section between Sections 1 & 12. Variation 10° East, at 19 8 1/2 chains fell 50 links North of temporary 1/6 Section corner. at 39.85 1/2 fell 18 links East of 1/4 Section corner. Thence South corrected Par 10° 31' East at 19.92 3/4 chains set post for 1/6 Section corner. It took 26 N 50 1/2 W 33 links. White oak 8 S 11 1/2 W 8.66 links. Thence South Par 7° 24' East 19.92 3/4 chains to quarter corner. From the of course center post 1/6 Section corner corrected East 20.16 chains Par 9° 32' East & also corrected West 20.06 chains Par 9° 50' East. Then from 1/4 Section corner on North side of said Section 1 ran West Variation 10° East. at 20.09 chains fell 109 links South of corner of Sections 1 & 2, 35 & 36 where I took new bearing in lieu of old one destroyed. It took 10 N 87 1/2 W 81 links. East corrected Par 8° 27' East at 20.09 chains set post for 1/4 Section corner in mound.

Then from corner of Sections 1, 2, 35 & 36 South Variation 10° East. at 38.62 chains fell 78 links West of quarter Section corner between Sections 1 & 2. Thence North corrected Variation 10° 25' East at 20.00 chains set post for 1/6 Section corner. Bearings It took 10 S 51 1/2 W 153 links. It took 12 N 72 W 167 links.

Thence East Variation 10° East at 40.15 chains fell 18 links South 1/6 Section corner. West corrected Variation 10° 11' East at 20.08 chains set temporary post for 1/6 Section corner.

Then from 1/4 Section corner West of center post of said Section ran North. Variation 10° 40' East. at 20.18 chains intersect at 1/6 Section corner. at 38.32 chains fell 19 links East West 1/4 Section corner on Down line. Then corrected South 18.22 chains & set post for 1/6 Section corner in mound. Thence corrected East 20.08 chains Par 8° 43' East.

A true copy of note of said Survey. Witness my hand and seal this 19<sup>th</sup> day of June 1854. Attest. John G. Clark, County Surveyor