

7 corrected East and West lines at 60.33 1/4 chains  
 set 1/8 part the N.E. corner of the said West 1/2 of the  
 N.E. 1/4 of Section 21.

Then run from corner of Section 16. 1/2 20 & 21 South  
 on 8° 59' E at 40.42 chains intersect at 1/4 part Sprains  
 by established by myself corrected back 20.21 chains &  
 set 1/8 part then from the 1/4 part on West side of  
 Section 21 East on 8° 48' without chaining West  
 half <sup>mile</sup> at 40.59 <sup>chain</sup> intersect <sup>link</sup> 6 1/2 North of 1/4 part Sprains  
 by set by myself. Then from 1/4 part on South  
 side Section 21 ran North chaining from the  
 intersection of true East West line North at  
 40.42 <sup>chain</sup> intersect 17 links <sup>1/4 part</sup> West on 9° E. Then come  
 at 20.21 chains set 1/8 part and at 40.42 chains  
 set South & set 1/4 part in center of section  
 making the North 1/2 of line through center of  
 Section 40.42 chains & East 1/2 of East West line  
 through center of Section 40.55 chains Bar of  
 North South line through center 8° 53' E. of East West  
 line through center 8° 16' East. Then from center  
 part corrected East 20.16 1/2 chains & set 1/8 part the  
 S.E. corner of N.E. 1/4 of N.E. 1/4 Section 21.

Then beginning at 1/4 part on West side of  
 Section 22 ran 8° 45' E. having first sun in Henry  
 Young as chainman in lieu of Isaiah McMill  
 iam ran East through center of Section 21 at 81.51 chain  
 intersect 6 links South of 1/4 part from which bear  
 a Book 12 N 56° E 156 links and a Book 10 N 25 W 254 links  
 the latter having been taken in lieu of a Book 14 N 52 W 270  
 links which had been cut. Then from 1/4 part on  
 South side of Section 22 North through center of sec  
 tion ran 9° E & from intersection of true East West  
 line chained North at 40.20 chains intersect 35 links  
 West of 1/4 part. Then corrected South setting post  
 for 1/4 section corner in center of section at corner

20.21 20.50

8  
 of True East & West & North & South lines Making East  
 1/2 of East & West line 40.71 chains & West 1/2 40.65 chains  
 True Bar of North & South line through center of section 8° 58'  
 1/2 of East & West line through center 8° 48' E. Then corrected  
 East 20.55 1/2 and set 1/8 part where bears Book 10 & 10  
 N 15 W 50 links Book 10 N 33 1/2 E 10 links. Then from  
 1/4 part on North side of Section 22 ran East on 8° 35' E  
 at 40.57 chains intersect 11 links South of corner to sec  
 tion 14, 15, 22 & 23. from which bear a Book 13 S 63 E 55 1/2 links  
 and a Book 6 S 87 E 313 links. Then corrected West  
 at 20.58 1/2 <sup>chain</sup> set 1/8 part North & Book 8 N 68 W 111 links & Book  
 10 S 31 E 363 links.

A true record of the notes of said survey etc  
 entered the 8<sup>th</sup> & 9<sup>th</sup> of June 1853  
 John G. Clark  
 Deputy County Surveyor

No. 6.  
 Record of the notes of survey made on the 8<sup>th</sup> & 9<sup>th</sup>  
 days of June 1853 by John G. Clark for Frederick M.  
 Boyer of the E. 1/2 of the N.E. 1/4 of Section 21 & the South 1/2  
 of the N.W. 1/4 of the N.W. 1/4 of Section 22. Township 5 North  
 of Range 5 West.



Isaiah McMilliam & F. M. Boyer chainmen duly sworn  
 having first read and established the 1/4 parts &  
 Section parts around Section 21 as noted in pro  
 cess Survey & then <sup>having</sup> closed the section twice &