


# SURVEY PLAT

HOVELSRUD CONSULTING ASSOCIATES LTD.  
ENGINEERING - LAND SURVEYING - PLANNING  
BUILDINGS - STRUCTURES - SOIL INVESTIGATIONS  
RICHLAND COUNTY BANK BUILDING  
RICHLAND CENTER, WISCONSIN 53581


Description For: Production Credit Association February 23, 1978

Sheet 2 of 2

Parcel located partly in the Northeast Quarters (NE $\frac{1}{4}$ ) of the Northeast Quarter (NE $\frac{1}{4}$ ) and partly in the Southeast Quarter (SE $\frac{1}{4}$ ) of the Northeast Quarter (NE $\frac{1}{4}$ ) all in Section 9, 1.4 N., R.3 W., Grant County, Wisconsin.



Michael J. Miller  
Registered Land Surveyor S-1140



# SURVEY PLAT

HOVELSRUD CONSULTING ASSOCIATES LTD.  
ENGINEERING - LAND SURVEYING - PLANNING  
BUILDINGS - STRUCTURES - SOIL INVESTIGATIONS  
RICHLAND COUNTY BANK BUILDING  
RICHLAND CENTER, WISCONSIN 53581

DESCRIPTION FOR: Production Credit  
Association

February 23, 1978

Sheet 1 of 2

A DESCRIPTION OF A PARCEL OF LAND DESCRIBED AS FOLLOWS:

Commencing at the Southeast Corner of the Northeast Quarter (NE $\frac{1}{4}$ ) of Section 9, T. 4 N., R. 3 W., Grant County, Wisconsin; Thence North, 927.14 feet to the point of beginning;

Thence West, 280.46 feet;

Thence N 39°-17'-09" W, 217.16 feet to a point in the centerline of Wisconsin State Trunk Highway '81';


Thence N 50°-42'-51" E, 540.00 feet to a point in said centerline;

Thence South, 510.00 feet to the point of beginning;

The above described parcel being located partly in the Northeast Quarter (NE $\frac{1}{4}$ ) of the Northeast Quarter (NE $\frac{1}{4}$ ) and partly in the Southeast Quarter (SE $\frac{1}{4}$ ) of the Northeast Quarter, (NE $\frac{1}{4}$ ) all in Section 9, T. 4 N., R. 3 W., Grant County, Wisconsin, and containing 2.99 acres and being subject to conveyances for roadway purposes.

I certify that I have written the above description from existing records and that the following Plat is a true representation thereof to the best of my knowledge and belief.

Dated this 3rd day  
of March, 1978  
Richland Center, Wisconsin

  
Michael J. Miller  
Registered Land Surveyor S-1140

