

I certify that the above field notes are correct
Jan 12th 1854

Charles Dickey
Dept. Surveyor of Grant
County Wis.

A true Record.

Attest
John G. Clark
County Surveyor

No 38
Survey made for Askin Bradt & John
Borne the 5th day of January A D 1854 by Albert
W. Stuntz Deputy County Surveyor of the West
1/4 of S.E. 1/4 & S.W. 1/4 of N.E. 1/4 of Section 36 Township 6
North Range 6 West of 4th P.M.

Commencing at 1/4 Section post on East side of said
Section ^{ran then random 700} East at 20 chains set temporary
1/8 Section corner at 40 chains set temporary 1/4 Section
corner at 79.23 intersect Meridian Section line
13 links South of 1/4 Section post. Then from 1/4 Section
post on Town line at South ^{near} corner of said section
ran a random East at 79.80 fell 20 links South of
Corner of Township 5.56 North of Range 5.56 West. Hence
Corrected West 19.95 & set 1/8 Section corner White Oak
5 N 81° E 147 links to other near. Hence corrected West
19.95 & set 1/4 Section post. & took new bearings original
bearings being entirely destroyed. White ^{oak} North 117 links
White Oak 5 N 77° W 36 links. Hence ran a random
North through center of section at 20 chains set 1/16
temporary post at ^{37.69} ~~40~~ chains ^{intersect at 39 link to East} set temporary 1/16
Section post at 60 chains set temporary 1/16
Section post at 79.75 intersect Section line
20 links West of 1/4 Section corner.

7-4

Hence ran a random East at 20 chains set temporary 1/8
Section corner at 39.90 intersect Range line 10 links North
of corner of sections 25 & 36. Hence ran random
South at 20 chains set temporary 1/8 Section corner
at 39.88 chains fell 2 links East of 1/4 Section corner
Hence continued South at 20 chains
set temporary 1/16 Section corner at 39.97 chains
fell 9 links East corner of Township 5.56 North Range
5.56 West. Then from 1/8 Section corner on South
side of S.E. 1/4 of said section ran thence random
North through center of said South East Quarter
at 20 chains set temporary 1/16 Section post at
39.81 chains fell 15 links West of ^{true & corrected} 1/8 Section corner
Corrected & established same White Oak 12 S 70° W 95 links
Hence continued West through center of S.E. 1/4 of
said section at 20 chains set temporary 1/16 Section
corner at 39.91 chains intersect at true & corrected
1/8 Section corner. Hence corrected 1/16 Section corner on East side
of S.E. 1/4 of said section ~~at~~ then ran West at
19.86 intersect 6 links South of temporary 1/16 Section
corner at 39.75 intersect at true & corrected ~~at~~ 1/16 Section
corner on West side of S.E. 1/4 of said section
Corrected & established same ^{at} White Oak 13 S 82° E 24
Hence corrected East 19.87 1/2 & set 1/16 post White
Oak 13 S 52° W 39 links.

Hence corrected & established 1/16 post in center of section
White Oak 10 N 40° E 25 links. Then corrected & established
1/16 Section corner on West side of S.E. 1/4 of said section
White Oak 13 S 87° W 129. Then ran East through center
of S.E. 1/4 of said section & corrected West
and established 1/16 Section in center of said
Quarter Section White Oak 15 S 70° W 15 links.

John G. Clark County Surveyor
By A. C. Stuntz Deputy
A true Record. Attest J. G. Clark County Surveyor